# **EXHIBIT WW**

#### SUPPLEMENT TO REDWOOD LOCATION FACT REPORT

#### **Supplemental Background Information:**

On June 8, 2018 CAL FIRE released its Final Report, 17CAMEU012169 ("CAL FIRE Report"). This report is publicly available via the following link on the CAL FIRE website: http://calfire.ca.gov/fire\_protection/downloads/FireReports/LE-80%20Redwood%20Incident%20Report\_Redacted.pdf.

According to the CAL FIRE Report, CAL FIRE started receiving reports of a vegetation fire in Potter Valley at 11:34 PM.

#### **Supplemental Evidence Collection Information:**

In the CAL FIRE Report, CAL FIRE reported that it collected a portion of a 12kV conductor, a fulgurite, and a fulgurite with a portion of a conductor from the Redwood Incident Location.

#### **Supplemental Timeline Information:**

The Redwood Location Fact Report contained a timeline of PG&E's actions at or impacting the incident location within a three-hour window on either side of the start time designated by CAL FIRE in the April 20, 2018 communication, which was October 8, 2017, 11:30 PM. The following additional information is relevant to the Redwood Location Fact Report timeline.

- October 8, 11:34 PM: CAL FIRE started receiving reports of a vegetation fire in Potter Valley.
- October 9, 12:27 AM: A CAL FIRE Heavy Fire Equipment Operator reported a new vegetation fire at Hawn Creek Road and Main Street.

#### **Supplemental Information Regarding Prior Inspections:**

Between October 2012 and October 2017, there were thirteen vegetation management inspections at or near the incident location. PG&E's understanding based upon its records is that the subject tree was never identified for work. Between May 2014 and October 2017, there were two electric maintenance overhead patrols and one electric maintenance overhead inspection. PG&E's understanding based upon its records is that the subject poles were not identified for work. Between May 2013 and October 2017, there was one intrusive inspection. PG&E's understanding based upon its records is that the subject poles were not identified for work.

Below is a summary of vegetation management patrols and inspections, electric maintenance overhead patrols and inspections, and intrusive inspections performed at or near the incident location.

Date	Event	Findings
12/3/2012	Western Environmental Consultants,	PG&E's understanding based upon
	Inc. ("WECI") performed a vegetation	its records is that the subject tree
	management routine patrol.	was not identified for work.
1/4/13	WECI performed a vegetation	PG&E's understanding based upon
	management routine patrol.	its records is that the subject tree
		was not identified for work.
5/7/2013 -	A PG&E contractor performed an	PG&E's understanding based upon
5/29/2013	intrusive pole inspection.	its records is that the subject poles
		were not identified for work.
2/7/14-2/12/14	WECI performed a vegetation	PG&E's understanding based upon
	management routine patrol.	its records is that the subject tree
		was not identified for work.
5/5/2014	PG&E performed an electric	PG&E's understanding based upon
	maintenance overhead patrol.	its records is that the subject poles
	-	were not identified for work.
9/17/2014	A PG&E contractor performed a	PG&E's understanding based upon
	Catastrophic Event Memorandum	its records is that the subject tree
	Account ("CEMA") patrol.	was not identified for work.
2/3/2015-	WECI performed a vegetation	PG&E's understanding based upon
2/20/2015	management routine patrol.	its records is that the subject tree
		was not identified for work.
3/23/2015	PG&E performed an electric	PG&E's understanding based upon
	maintenance overhead inspection.	its records is that eight electric
	•	corrective forms were created, but
		the subject poles were not identified
		for work.
7/27/2015	A PG&E contractor performed a	PG&E's understanding based upon
	CEMA patrol.	its records is that the subject tree
		was not identified for work.
2/17/2016 -	WECI performed a vegetation	PG&E's understanding based upon
2/18/16	management routine patrol.	its records is that the subject tree
		was not identified for work.
3/17/16	WECI performed a vegetation	PG&E's understanding based upon
	management routine patrol.	its records is that the subject tree
		was not identified for work.
3/30/2016	PG&E performed an electric	PG&E's understanding based upon
	maintenance overhead patrol.	its records is that the subject poles
	-	were not identified for work.
8/5/2016	A PG&E contractor performed a	PG&E's understanding based upon
	CEMA patrol.	its records is that the subject tree
		was not identified for work.
10/17/2016	A PG&E contractor performed a	PG&E's understanding based upon
	CEMA patrol.	its records is that the subject tree
	_	was not identified for work.

## Case 3:14-cr-00175-WHA Document 956-49 Filed 12/31/18 Page 4 of 6

Date	Event	Findings
2/27/2017-	WECI performed a vegetation	PG&E's understanding based upon
2/28/2017	management routine patrol.	its records is that the subject tree
		was not identified for work.
7/20/2017	WECI performed a CEMA patrol.	PG&E's understanding based upon
		its records is that the subject tree
		was not identified for work.
8/8/2017	WECI performed a CEMA patrol	PG&E's understanding based upon
		its records is that the subject tree
		was not identified for work.

### **Source List:**

Source	Brief Description
August 2014 Patrol	August 2014 CEMA Patrol of the Potter Valley 1105 Circuit
CAL FIRE Report	CAL FIRE Investigation Report 17CAMEU012169, Redwood, <a href="http://calfire.ca.gov/fire_protection/downloads/FireReports/LE-80%20Redwood%20Incident%20Report_Redacted.pdf">http://calfire.ca.gov/fire_protection/downloads/FireReports/LE-80%20Redwood%20Incident%20Report_Redacted.pdf</a>
December 2012	December 2012 routine vegetation inspection of the Potter
Inspection	Valley 1105 Circuit
February 2014	February 2014 routine vegetation inspection of the Potter
Inspection	Valley 1105 Circuit
February 2015	February 2015 routine vegetation inspection of the Potter
Inspection	Valley 1105 Circuit
February 2016	February 2016 routine vegetation inspection of the Potter
Inspection	Valley 1105 Circuit
February 2017	February 2017 routine vegetation inspection of the Potter
Inspection	Valley 1105 Circuit
PGE-CPUC_00009688- 00009736	Electric Maintenance Overhead Inspection Records
PGE-CPUC_00009683; PGE-CPUC_00009737; PGE-CPUC_00009686; PGE-CPUC_00009739	Electric Maintenance Overhead Patrol Records
PGE-CF_00004843; PGE-CF_00004849	Pole Inspection Records
PGE-CF 00142703;	Vegetation Management CEMA Maps
PGE-CF 00142705;	
PGE-CPUC_00012645;	
PGE-CPUC_00012647;	
PGE-CPUC_00020768;	
PGE-CPUC_00020769	
PGE-CPUC_00020762;	Vegetation Management Inspection Records
PGE-CPUC_00020760; PGE-CPUC_00020758-	
00020759	
PGE-CPUC 00020756;	Vegetation Management Work Requests
PGE-CPUC_00020762-	

## Case 3:14-cr-00175-WHA Document 956-49 Filed 12/31/18 Page 6 of 6

00020763; PGE-	
CPUC_00020757;	
PGE-CPUC_00020761	
PGE-CPUC_00011183;	Yearly CEMA Projects
PGE-CPUC_00011388;	
PGE-CPUC_00011471;	
PGE-CPUC_00011986	
_	